


Model: AP-C3		Date: 04-Mar-13	No.: RD144069
Subject: Parts change information.		Prepared by: H. Tamaki	
From: 1st Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input checked="" type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input type="checkbox"/> Other ()	<input type="checkbox"/> Tier 2

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D1446286	D1446274	CASE:TRANSFER ROLLER	1	X/X	-	-	
D0894663	D0894664	GUIDE PLATE:TRANSFER UNIT:HOLDER	1	X/X			
	D0894665	SHAFT:HOLDER:REAR	1	X/X	-	-	-
	04583010N	HEXAGON HEAD TAPPING SCREW:3X10	1	X/X	-	-	-
	D0894666	DRUM STAY:FRONT	1	X/X	-	-	-
	04583008N	HEXAGON HEAD TAPPING SCREW:3X8	2	X/X	-	-	-

Change: The material of the parts was changed from a resin to a metal.

Reason: To further increase the load-bearing strength of the parts.

Important: Interchangeability is **X/O** as a set (all six parts together).



Model: AP-C3	Date: 04-Mar-13	No.: RD144069
--------------	-----------------	---------------

